



Rule Changes from the Executive

Issue #2017-4 Published 16-8-17

Updates underlined:

Add following new Rule:

Q5.6 Accredited KartSport Coach Exceptions: Accredited KartSport New Zealand Coaches are permitted to:

- During test days only, operate one-way radio communication Coach to Pupil while the pupil is on track.
NOTE: Not permitted on test days immediately prior to Group A, Group B, Group C, Group D or Group E events.
- During test days only, undertake, in a senior specification kart, on track coaching of a Cadet, Junior Restricted or Junior Age Group Pupil in their respective specification kart. At any one time only the Coach and Pupil are permitted on track together.
NOTES: Not permitted on test days immediately prior to Group A, Group B, Group C, Group D or Group E events. Subject to host Club's class sequencing should other drivers wishing to test be present (eg prior to Group F Club Days).

Implementation: 18-8-17

Reason: To verify the revamped Accredited Coaches programme which includes Accredited Coaches being able to undertake one on one Explore & Learn and Hot Shots courses and issue observations/stamps towards upgrading/fast tracking a competitor's Licence Rating towards Tier 1 and/or Tier 2 status.

Rotax FR125 Max Rule N12.2
Add the following to Rule N12.2

- Welding of the external water jacket only is allowed to repair cracks. The welding may only be carried out on the external surface of the water jacket. Only localized spot facing the external water jacket/cylinder head cover mating surface is permitted to restore the cylinder sealing surface as required where the weld intrudes.

Implementation: 1-10-17

Reason: Round 32 support from Clubs. To permit a non-performance enhancing repair.

Rotax FR125 Junior Max Rule N14.2
Add the following to Rule N14.2

- Welding of the external water jacket only is allowed to repair cracks. The welding may only be carried out on the external surface of the water jacket. Only localized spot facing the external water jacket/cylinder head cover mating surface is permitted to restore the cylinder sealing surface as required where the weld intrudes.

Implementation: 1-10-17

Reason: Round 32 support from Clubs. To permit a non-performance enhancing repair.

Rotax 125 Max DD2 Rule N16.2
Add the following to Rule N16.2

- Welding of the external water jacket only is allowed to repair cracks. The welding may only be carried out on the external surface of the outer jacket. Only localized spot facing the external water jacket/cylinder head cover mating surface is permitted to restore the cylinder sealing surface as required where the weld intrudes.

Implementation: 1-10-17

Reason: Round 32 support from Clubs. To permit a non-performance enhancing repair.